

4505 188th St. SW, Lynnwood, WA (S-7)



Smoke seen from unknown source



Unknown source of smoke alongside driveway

18827 48th St, Lynnwood, WA (S-8)



Northeast side of house



Smoke seen emanating from hole in ground

19427 40th Ave W, Lynnwood, WA (S-9)



Smoke seen from loose cleanout cap on northeast side of building

4114 186th St. SW, Lynnwood, WA (S-10)



View of house and driveway




Smoke emanating from joint of driveway and planter

18705 44th Ave, Lynnwood, WA (S-11)



Smoke emanating from hole in ground.

4108 186th Pl. SW, Lynnwood, WA (S-12)



Front of house at 4108 186th Pl. SW in Lynnwood



Smoke emanating from pipe.

18632 42nd Ave, Lynnwood, WA (S-13)



Smoke emanating from downspout on west side of house

4312 189th PL. SW, Lynnwood, WA (S-14)



Smoke seen in back yard.

Front of house at 4312 189th Pl. SW in Lynnwood.



Smoke seen in back yard.

19701 48th Ave, Lynnwood, WA (S-15)



Smoke emanating from hole in cleanout cover

48th Ave W in Park and Ride Facility in Lynnwood, WA (S-16)



Area view where smoke is emanating from shrubs.



Smoke emanating from shrubs.

4305 189th Pl. SW, Lynnwood, WA (Problem #17)



View of empty lot where smoke is emanating from hole in ground.



Smoke emanating from hole in ground.



Smoke above hole in ground.



View inside hole where smoke is emanating from.

18427 42nd Pl. W, Lynnwood, WA (S-18)



Front entryway of house at 18427 42nd Pl. W in Lynnwood.



Smoke emanating from edge of concrete.

18638 44th Ave. W, Lynnwood, WA (Lynnwood Elementary (A)) (S-19)



Located near
the large rock

South side of school



Uncapped cleanout at grade.



View from above looking inside uncapped cleanout.

18639 44th Ave. W, Lynnwood, WA (Lynnwood Elementary (B)) (S-20)



View of surrounding area near smoke.



Smoke emanating at joint of concrete and grass.

4419 200th Ave In back of JD's Market (S-21)



Smoke emanating from loose cleanout cap.

18320 44th Ave W, Lynnwood, WA (S-22)



Smoke seen coming from rockery on west side of lot.



Smoke emanating from base of rockery and adjacent ground.

5108 196th St. SW, Lynnwood, WA (S-23)



View of east side of building at 5108 196th St SW in Lynnwood.



Smoke emanating from downspout.

Southwest corner of Scriber Lake Ave and 198th St. SW, Lynnwood, WA (S-24)



Smoke emanating from crack in sidewalk and joint with planter.

5824 196th St SW, Lynnwood, WA (Jo-Ann Fabric) (S-25)



Southwest corner of Jo-Ann Fabric



Smoke emanating from joint of concrete and grass.

S-26 to S-53

Problems S-26 through S-53 were identified through the 1992 study. No photos were available for these problems. See the smoke testing results logs seen at the end of the Appendix.

6013 178th St. SW, Lynnwood, WA (S-54)




Smoke seen from downspout

Downspout connected to sanitary sewer on east side of house.



Smoke emanating from downspout.

5813 182nd Pl. SW, Lynnwood, WA (S-55)



Drain located behind flower pots at the bottom of the driveway

View of front of house at 5813 182nd Pl. SW in Lynnwood.



Storm drain

Smoke emanating from drain.

6209 183rd Pl. SW, Lynnwood, WA (S-56)



Smoke seen
under bush

View of smoke emanating from bush and surrounding area.



Smoke emanating from bush.

18416 61st Pl. W, Lynnwood, WA (S-57)



Loose concrete cleanout cap at grade.

6230 186th St. SW, Lynnwood, WA (S-58)



Smoke seen from cleanout in the backyard near pool.



Smoke seen from cleanout with pipe running into it.



Loose cleanout cap.

6026 180th St. SW, Lynnwood, WA (S-59)



Downspouts connected to sanitary sewer.



View of house at 6026 180th St SW in Lynnwood

6319 177th Pl. SW, Lynnwood, WA (S-60)



Smoke emanating from multiple downspouts.



Smoke emanating from downspout on southeast corner of roof.

6319 177th Pl. SW, Lynnwood, WA (S-60)



Smoke emanating from downspout on northeast corner of roof.

18630 60th Ave W, Lynnwood, WA (S-61)



Smoke emanating from downspout on northwest side of house.

6112 178th St. SW, Lynnwood, WA (S-62)



Smoke emanating from leaky cover.



View of driveway at 6112 178th St. SW in Lynnwood

5902 183rd St. SW, Lynnwood, WA (S-63)



View of front of house at 5902 183rd St. SW in Lynnwood.



Smoke emanating from drain at base of driveway

6031 189th Pl. SW, Lynnwood, WA (S-64)



Smoke emanating from under front porch step.

6131 Park Way, Lynnwood, WA (S-65)



View of front of 6131 Park Way in Lynnwood.



Smoke emanating from exposed pipe at base of front steps.

6303 188th St. SW, Lynnwood, WA (S-66)



Smoke emanating from uncapped cleanout in yard.



Area surrounding uncapped cleanout.

6605 188th St. SW. Lynnwood, WA (S-67)



Front of house at 6605 188th St. SW in Lynnwood



Smoke emanating from uncapped pipe

20612 Hwy 99, Lynnwood, WA (S-68)



Car wash at Jack Carroll's Lynnwood Dodge



Under carport inside car wash looking at grate

20612 Hwy 99, Lynnwood, WA (S-68)



Smoke emanating from grate under carport

20014 68th Ave W. Lynnwood, WA (S-69)



Jack Carroll's Lynnwood Dodge



Smoke emanating from uncapped pipe



Side view of front of property

20014 68th Ave W. Lynnwood, WA (S-69)



Area surrounding uncapped pipe



House at 20014 68th Ave. W. in Lynnwood

Intersection of 196th St SW and 68th Ave W in Lynnwood, WA (S-70)



Smoke emanating from manhole cover



View of intersection with smoke emanating from manhole

6326 186th St SW, Lynnwood, WA (S-71)



Area surrounding water meter box



Smoke emanating from water meter box cover

6326 186th St SW, Lynnwood, WA (S-71)



View looking down on top of water meter box

6629 204th St SW, Lynnwood, WA (S-72)



Downspout on front of house



Building at 6629 204th St. SW in Lynnwood

6629 204th St SW, Lynnwood, WA (S-72)



Smoke emanating from downspout

Near 6511 and 6533 208th St. SW, Lynnwood, WA (S-73)



Looking inside manhole



Area surrounding manhole.

Near 6511 and 6533 208th St. SW, Lynnwood, WA (S-73)



Woods adjacent to manhole.

Near 6506, 6512 and 6514 208th St. SW in Lynnwood, WA (S-74)



Area surrounding manhole



Smoke emanating from manhole

Near 6506, 6512 and 6514 208th St. SW in Lynnwood, WA (S-74)



Smoke emanating from base of manhole cover



Smoke emanating from base of manhole cover

6518 208th St. SW, Lynnwood, WA (adjacent to parking stall #266) (S-75)



View of property looking north

6518 208th St. SW, Lynnwood, WA (adjacent to parking stall #266) (S-75)



Smoke emanating from cleanout cap



View looking west at building near leaky cleanout



Looking inside cleanout

6518 208th St. SW, Lynnwood, WA (adjacent to parking stall #266) (S-75)



Close-up view of inside of cleanout

20107 68th Ave. W., Lynnwood, WA (S-76)



Back side of building at 20107 68th Ave. W. in Lynnwood



Area where smoke emanated from ground

20107 68th Ave. W., Lynnwood, WA (S-76)



Area surrounding area where smoke emanated from ground

20113 68th Ave. W., Lynnwood, WA (in front of Divan Café) (S-77)



Area surrounding cleanout in street



Smoke emanating from hole in cleanout cover

6001 202nd St. SW, Lynnwood, WA (S-78)



Southwest corner of lot.



Smoke emanating from unknown source in shrubs.

6001 202nd St. SW, Lynnwood, WA (S-79)



Area surrounding source of smoke.



Smoke emanating from uncapped pipe.

6109 208th St. SW, Lynnwood, WA (S-80)



View of south side of house.



Smoke emanating from uncapped cleanout.

6208 204th St. SW, Lynnwood, WA (S-81)



Area surrounding cleanout.



Smoke emanating from loose cleanout cap.