


Parks, Trails, and Buildings



Facility Type

- Trail
- Building
- ⊙ See Note Below


Context

- Water Feature
- Streets
- Park
- City Limits

The Meadowdale Playfields ballfields were under construction and the Lynnwood Development and Business Services office was under lease negotiation at the time of the barrier assessments. Any barriers identified at these facilities will be incorporated into the City's ADA barrier analysis tool and transition plan schedule maintained by the City's ADA coordinator.



Barrier Removal Projects: Curb Ramps



City Responsibility Barrier Removal Rank

- No Deficiencies Identified
- Low Priority
- Medium Priority
- High Priority
- Recent and Near-Term Project

Shared Responsibility Barrier Removal Rank

- ▲ No Deficiencies Identified
- ▲ Low Priority
- ▲ Medium Priority
- ▲ High Priority


Context

- Water Feature
- Streets
- Park
- - - City Limits

January 2021



Pedestrian Access Route Barrier Removal Projects: Sidewalks



Barrier Removal Rank

- High Priority
- Medium Priority
- Low Priority
- No Deficiencies Identified
- Recent and Near-Term Project


Context

- Water Feature
- Streets
- Park
- City Limits

January 2021



Pedestrian Access Route Barrier Removal Projects: Driveways



Barrier Removal Rank

- High Priority
- Medium Priority
- Low Priority
- No Deficiencies Identified

Context

- Water Feature
- Streets
- Park
- City Limits

January 2021

