

Lynndale Elementary School Assessment Finding



Lynndale ES

The loop is also a fire lane, so parents cannot queue in the loop before bell time
4 bikes, 2 scooters observed in bike rack

Bus designated queue zone
Students jaywalk before crosswalk

Some parents park their vehicle on 192nd Pl SW and pick up their children

No sidewalk and drivers queue on 189th Pl SW

Vehicle line obstructs pedestrian visibility

Marked crosswalk leading to the park's parking lot

Few vehicles line up on 70th Ave W

Few students walking
Poor visibility due to vegetation and curve

Loop limited to right in & out but some parents still try to turn left

Parents park along 191st Pl SW and walk through bus queue to pick-up students

Many walkers on 192nd Pl SW heading towards 68th Ave W

Essential missing sidewalk
60+ walkers observed walking south from school

No marked crosswalk at 190th St SW. The closest crosswalk north is on 188th St SW. No students observed crossing 68th north of 192nd Place

Flashing beacon present but unlikely that students can cross 68th Ave without the help of Safety Patrol person

- Pedestrian Movement
- Vehicle Movement
- Missing Sidewalk
- Suggested Walk Routes
- Bike Lanes
- School Crosswalk Warning
- Marked Crosswalk
- Traffic Signal
- Adult Safety Patrol
- Student Safety Patrol